

13
DIOXIN REPORT 05/08/89



S00180322
SUPERFUND RECORDS

RL SITE: MANCHESTER PUBLIC WORKS

SITE	EPA NO	VALUE	VALID	UNITS	DESCRIPTION
------	--------	-------	-------	-------	-------------

DATE	LAB
SAMPLED	

222845

MPW	AK0966	B	0.400U	V	NG/GM	CONTROL SAMPLE-NORTH SIDE OF 2ND STREET APPROX. 60' WEST OF DON'S AUTO
MPW	AK0967		0.400U	V	NG/GM	GRASS STRIP EAST EDGE OF ASPHALT PARKING AREA DEPTH 4-8"
MPW	AK0968	D	0.400U	V	NG/GM	GRASS STRIP EAST EDGE OF ASPHALT PARKING AREA DEPTH 4-12" (QC0967)
MPW	AK0969		0.100U	V	NG/GM	GRAVEL AREA TO SOUTHWEST OF ASPHALT PARKING AREA DEPTH 4-12"
MPW	AK0970		0.100U	V	NG/GM	SOIL BENEATH THE ASPHALT PARKING AREA EAST OF MANCHESTER P.W. BUILDING
MPW	AK0972		0.100U	V	NG/GM	WOODS ALONG FENCE ON SOUTH SIDE STORAGE AREA (DRAINAGE AREA)

12/08/82	CAL
12/08/82	CAL
12/08/82	CAL
12/08/82	WSU
12/08/82	WSU
12/08/82	WSU